



January 2005 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?</p>		<p>Check Air Permit. Paint & solvent usage records may be required.</p>			<p>STP <input type="checkbox"/></p>	<p>1 New Year's Day</p>
2	3	4	5	6	<p>7 STP <input type="checkbox"/></p>	8
9	10	11	<p>12 Hazardous Waste Rpt.Workshop-W. Monroe (318) 397-6130</p>	<p>13 Hazardous Waste Rpt.Workshop-Shreveport/Alex. (318) 676-7811</p>	<p>14 STP <input type="checkbox"/></p>	15 **
16	<p>17 Martin L. King, Jr. Day</p>	<p>18 Hazardous Waste Rpt.Workshop-Laf./Lk. Charles (337) 262-5962</p>	<p>19 Hazardous Waste Rpt.Workshop-Metairie (504) 736-7072</p>	<p>20 Hazardous Waste Rpt.Workshop-Baton Rouge (225) 219-3248</p>	<p>21 STP <input type="checkbox"/></p>	22
23	24	25	26	27	<p>28 ** STP <input type="checkbox"/></p>	29
30	31	<p><u>LEHA CONFERENCE - LaPlace</u></p>		<p>Discharge Monitoring Report Due</p>		

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



February 2005 Small Business Reporting Calendar



ALERT: Check Reports Due March 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?</p>		1	2	3	4 STP <input type="checkbox"/>	5
6	7	8	9	10	11 STP <input type="checkbox"/>	12 Lincoln's Birthday
13	14 Valentine's Day	15 **	16	17	18 STP <input type="checkbox"/>	19 Annual Air Emission Report due
20	21 Presidents' Day	22 Washington's Birthday	23	24	25 STP <input type="checkbox"/>	26
27	28 **	 Mardi Gras	 Ash Wednesday		 STP <input type="checkbox"/>	 Check Air Permit. Paint & solvent usage records may be required.

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



March 2005 Small Business Reporting Calendar



ALERT: Check Reports due April 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Paint & solvent usage records may be required.	For <u>sanitary treatment plants (STP)</u>, check <u>weekly</u>: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?		<h3 style="margin: 0;">Questions? 1-800-259-2890</h3>			
		1 Hazardous Waste Annual Report; Tier II Report due	2	3	4 STP <input type="checkbox"/>	5
6	7	8	9	10	11 STP <input type="checkbox"/>	12
13	14	15 **	16 Solid Waste Operator Exam-LAF <u>DEQ's Annual Waste Conference-Lafayette, LA</u>	17	18 STP <input type="checkbox"/>	19
20	21 **	22	23	St. Patrick's Day 24	25 STP <input type="checkbox"/>	26
27	28	29	30	31 EIS Report due		

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



April 2005 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?</p>		<p># Title V Annual Compliance Certification and Title V Semi-annual Monitoring Reports due April 1st Questions? 1-800-259-2890</p>			<p>1 # STP <input type="checkbox"/></p>	<p>2 Check Air Permit. Paint & solvent usage records may be required.</p>
		<p>3 Daylight Savings Time Begins Palm Sunday</p>	<p>4</p>	<p>5 Passover</p>	<p>6</p>	<p>7</p>
<p>10 Easter</p>	<p>11</p>	<p>12</p>	<p>13</p>	<p>14</p>	<p>15 ** STP <input type="checkbox"/> Federal Income Taxes due</p>	<p>16</p>
<p>17</p>	<p>18</p>	<p>19</p>	<p>20 Administrative Professionals Day</p>	<p>21 Earth Day</p>	<p>22 STP <input type="checkbox"/></p>	<p>23</p>
<p>24</p>	<p>25</p>	<p>26</p>	<p>27</p>	<p>28 ** Discharge Monitoring Report Due</p>	<p>29 STP <input type="checkbox"/></p>	<p>30</p>

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



May 2005 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2	3	4	5	6 STP <input type="checkbox"/>	7 Ozone Season Begins
8 Mother's Day	9	10	11	12	13 STP <input type="checkbox"/>	14
15 ** Louisiana taxes due	16	17	18	19	20 STP <input type="checkbox"/>	21 Armed Forces Day
22	23	24	25	26	27 STP <input type="checkbox"/>	28 **
29	30	31 Waste Tire Transportation Renewal Due	For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?		QUESTIONS? 1-800-259-2890	Check Air Permit. Paint & solvent usage records may be required.

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



June 2005 Small Business Reporting Calendar



ALERT: Check Reports due July 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For <u>sanitary treatment plants (STP)</u>, check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?</p>			1	2	3 STP <input type="checkbox"/>	4
5	6	7	8	9	10 STP <input type="checkbox"/>	11
12	13	14 Flag Day	15 **	16	17 STP <input type="checkbox"/>	18
19 Father's Day	20	21	22	23	24 STP <input type="checkbox"/>	25
26	27	28 **	29	30 Waste tire transporter certificates expire	QUESTIONS? 1-800-259-2890	Check Air Permit. Paint and solvent usage records may be required.

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



July 2005 Small Business Reporting Calendar



DEQ permit maintenance fee invoicing begins. Pay by due date to keep active.

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?			Check Air Permit. Paint & solvent usage records may be required.		1 STP <input type="checkbox"/> TEDI; Form R(TRI); Minor Source Air Toxic Rpts; and PERC Report due	2
3	4 Independence Day	5	6	7	8 STP <input type="checkbox"/>	9
10	11	12	13	14	15 ** STP <input type="checkbox"/>	16
17	18	19	20	21	22 STP <input type="checkbox"/>	23
24	25	26	27	28 ** Discharge Monitoring Report Due	29 STP <input type="checkbox"/>	30
/ 31					QUESTIONS? 1-800-259-2890	

*Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections. *

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



August 2005 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
QUESTIONS? 1-800-259-2890	1 Ann. Rpt. for generators, processors, disposers of solid waste due	2	3	4	5 STP <input type="checkbox"/>	6
7	8	9	10		12 STP <input type="checkbox"/>	13
14	15 **	16	17	18	19 STP <input type="checkbox"/>	20
21	22	23	24	25	26 STP <input type="checkbox"/>	27
28 **	29	30	31	Check Air Permit. Paint & solvent usage records may be required.	For <u>sanitary treatment plants (STP)</u> , check <u>weekly</u> : (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



September 2005 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Paint & solvent usage records may be required.	For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?			1	2 STP <input type="checkbox"/>	3
4	5 Labor Day	6	7	8 Asbestos & Lead Workshop, DEQ Conf. Center	9 STP <input type="checkbox"/>	10
11	12	13	14	15 ** Rosh Hashanah	16 STP <input type="checkbox"/>	18
18	19	20	21	22	23 STP <input type="checkbox"/>	24 Yom Kippur
25	26 Title V Semiannual Monitor Report due	27	28 **	29 Ozone Season Ends	30	QUESTIONS? 1-800-259-2890

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



October 2005

Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?		Check Air Permit. Paint & solvent usage records may be required.		Questions? 1-800-259-2890		1
2	3	4	5	6	7 STP <input type="checkbox"/>	8
9	10 Columbus Day	11	12	13	14 STP <input type="checkbox"/>	15 ** National Boss Day
16	17	18	19	20	21 STP <input type="checkbox"/>	22
23 30 * & ** Daylight Savings Time Ends	24 31 Halloween	25	26	27	28 ** STP <input type="checkbox"/> Discharge Monitoring Report Due	29

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



November 2005

Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Paint & solvent usage records may be required.	Questions? 1-800-259-2890		For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?			
	All Saints' Day	1 UST worker certificate renewals due	2	3	4 STP <input type="checkbox"/>	5
6	7	8 Election Day	9	10	11 STP <input type="checkbox"/> Veterans' Day	12
13	14	15 **	16	17	18 STP <input type="checkbox"/>	19
20	21	22	23	24	25 STP <input type="checkbox"/>	26
27	28 **	29	30	Thanksgiving Day		

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



December 2005 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For sanitary treatment plants (STP), check weekly: (1)compressor, (2)chlorine in chlorinator & in contact with wastewater?; (3)foul odors from discharge , is discharge cloudy?</p>		<p>Check Air Permit. Paint & solvent usage records may be required.</p>	<p>QUESTIONS? 1-800-259-2890</p>	<p>1</p>	<p>2 STP <input type="checkbox"/></p>	<p>3</p>
<p>4</p>	<p>5</p>	<p>6</p>	<p>7 Hanukkah</p>	<p>8</p>	<p>9 STP <input type="checkbox"/></p>	<p>10</p>
<p>11</p>	<p>12</p>	<p>13</p>	<p>14</p>	<p>15 **</p>	<p>16 STP <input type="checkbox"/></p>	<p>17</p>
<p>18</p>	<p>19</p>	<p>20</p>	<p>21</p>	<p>22</p>	<p>23 STP <input type="checkbox"/></p>	<p>24</p>
<p>25 Christmas</p>	<p>26</p>	<p>27</p>	<p>28 **</p>	<p>29</p>	<p>30 STP <input type="checkbox"/> UST workers certificates expire</p>	<p>31 New Year's Eve</p>

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)