



January 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
<p style="color: red; font-weight: bold;">Check Air Permit. Keep paint & solvent usage records if required.</p>	1	2	3	4	5	6	
							STP <input type="checkbox"/>
	New Year's Day						
	7	8	9	10	11	12	13
							STP <input type="checkbox"/>
<p style="color: red; font-weight: bold;">UST Training - Baton Rouge (225) 219-3713 1-5 pm</p>							
14	15	16	17	18	19	20	
						STP <input type="checkbox"/>	
<p style="color: red; font-weight: bold;">**</p> <p style="color: red; font-weight: bold;">Martin L. King, Jr. Day</p>							
21	22	23	24	25	26	27	
						STP <input type="checkbox"/>	
<p style="color: red; font-weight: bold;">UST Training - Baton Rouge (225) 219-3713 1-5 pm (if needed)</p>							
28	29	30	31	<p style="color: red; font-weight: bold;">Ann.;Semi-ann.; & Qtr. DMRs Due</p>			
						STP <input type="checkbox"/>	
<p style="color: red; font-weight: bold;">SWAT-Alexandria (318) 487-5439 8-12 Noon</p>						<p style="color: red; font-weight: bold;">For <u>sanitary treatment plants (STP)</u>, check <u>weekly</u>: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?</p>	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



February 2007 Small Business Reporting Calendar



ALERT: Check Reports Due March 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?</p>				1 UST Worker Certification Exam (225) 219-3062	2 STP <input type="checkbox"/>	3
4	5	6	7	8	9 STP <input type="checkbox"/>	10
11	12	13	14	15 ** UST Training - Shreveport (225) 219-3713 8-12 Noon	16 STP <input type="checkbox"/>	17
18	19	20 Mardi Gras	21	22	23 STP <input type="checkbox"/>	24
25	26	27 SWAT- Baton Rouge (225) 219-3719 8-12 Noon	28 **	QUESTIONS? Call: 1-259-2890		Check Air Permit. Keep paint & solvent usage records if required.

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



March 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
<p>For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?</p>			<p>Response Action Contractor Renewals Due March 1st</p>	<p>1 Hazardous Waste Annual Report; Tier II Report Due</p>	<p>2 STP <input type="checkbox"/></p>	<p>3</p>	
<p>4</p>	<p>5</p>	<p>6</p>	<p>7</p>	<p>8</p>	<p>9 STP <input type="checkbox"/></p>	<p>10</p>	
<p>11 Daylight Saving Time Begins</p>	<p>12</p>	<p>13 UST Training - Lafayette (225) 219-3713 8-12 Noon</p>	<p>14</p>	<p>15 **</p>	<p>16 STP <input type="checkbox"/></p>	<p>17</p>	
<p>18</p>	<p>19</p>	<p>20</p>	<p>21 <u>2007 LSWA Environmental Conference, Lafayette, LA</u></p>		<p>22</p>	<p>23 STP <input type="checkbox"/></p>	<p>24</p>
<p>25</p>	<p>26</p>	<p>27 SWAT-Covington TBA (225) 219-3720 8-12 Noon</p>	<p>28 **</p>	<p>29</p>	<p>30 STP <input type="checkbox"/></p>	<p>31 Annual Emission Inventory Report (EI) Due</p>	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



April 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1	2	3	4	5 UST Worker Certification Exam (225) 219-3062	6 STP <input type="checkbox"/> Good Friday	7
8 Easter	9	10	11	12	13 STP <input type="checkbox"/>	14
15 **	16 Federal Income Taxes Due	17	18 UST Training - New Orleans (225) 219-3713 1-5 pm	19	20 STP <input type="checkbox"/>	21
22	23	24	25	26 SWAT- Lafayette (337) 262-5962 8-12 Noon	27 STP <input type="checkbox"/>	28 ** Quarterly DMR Due
29	30	For <u>sanitary treatment plants (STP)</u>, check <u>weekly</u>: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?				Check Air Permit. Keep paint and solvent usage records if required.

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



May 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Keep paint & solvent usage records if required.		1	2	3	4 STP <input type="checkbox"/>	5
	Ozone Season Begins (May through September)					
6	7	8	9	10	11 STP <input type="checkbox"/>	12
13	14	15 ** Louisiana State Income Taxes Due	16 UST Training - Lake Charles (225) 219-3713 8-12 Noon	17	18 STP <input type="checkbox"/>	19
20	21	22	23 SWAT- Thibodaux (225) 219-3720 8-12 Noon	24	25 STP <input type="checkbox"/>	26
27	28 ** Memorial Day	29	30	31	For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



June 2007 Small Business Reporting Calendar



ALERT: Check Reports due July 1st

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?</p>			<p>Check Air Permit. Keep paint and solvent usage records if required.</p>		<p>1 STP <input type="checkbox"/></p>	<p>2</p>
3	4	5	6	<p>7</p> <p style="text-align: center;">UST Worker Certification Exam (225) 219-3062</p>	<p>8 STP <input type="checkbox"/></p>	9
10	11	12	13	14	<p>15 STP <input type="checkbox"/> **</p>	16
17	18	19	20	21	<p>22 STP <input type="checkbox"/></p>	23
24	25	26	27	<p>28 **</p> <p style="text-align: center;">UST Training - Alexandria, 8-12N (225) 219-3713</p>	<p>29 STP <input type="checkbox"/></p>	30

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

****Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)****



July 2007 Small Business Reporting Calendar



DEQ permit maintenance fee invoicing begins. Pay by due date to keep active.

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
1 TEDI; Form R(TRI); Minor Source Air Toxic Rpts; and PERC Report Due	2	3	4 Independence Day	5	6 STP <input type="checkbox"/>	7
8	9	10	11 UST Training - Baton Rouge (225) 219-3713 1-5 pm	12	13 STP <input type="checkbox"/>	14
15 **	16	17	18	19 UST Training - Baton Rouge (225) 219-3713 1-5 pm (if needed)	20 STP <input type="checkbox"/>	21
22	23	24	25 SWAT- W. Monroe (318) 397-6100 12:30-4:30 pm	26 SWAT- Shreveport (318) 676-7811 8-12 Noon	27 STP <input type="checkbox"/>	28 ** Semi-annual & Qtr. DMR Due
29	30	31	For <u>sanitary treatment plants (STP)</u>, check <u>weekly</u>: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?		Check Air Permit. Paint & solvent usage records may be required.	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



August 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?</p>			<p>1</p> <p>Ann. Rpt. for Generators, Processors, Disposers of Solid Waste Due</p>	<p>2</p> <p>UST Worker Certification Exam (225) 219-3062</p>	<p>3 STP <input type="checkbox"/></p>	<p>4</p>
		<p>5</p>	<p>6</p>	<p>7</p>	<p>8</p>	<p>9</p>
<p>12</p>	<p>13</p>	<p>14</p>	<p>15 **</p>	<p>16</p>	<p>17 STP <input type="checkbox"/></p>	<p>18</p>
<p>19</p>	<p>20</p>	<p>21</p>	<p>22</p> <p>UST Training - Shreveport (225) 219-3713 8-12 Noon</p>	<p>23</p>	<p>24 STP <input type="checkbox"/></p>	<p>25</p>
<p>26</p>	<p>27</p>	<p>28 **</p>	<p>29</p> <p>SWAT- Livingston Parish (225) 219-3720 8-12 Noon</p>	<p>30</p>	<p>31 STP <input type="checkbox"/></p>	<p>Check Air Permit. Keep paint & solvent usage records if required.</p>

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



September 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
<p>Check Air Permit. Keep paint & solvent usage records if required.</p>	<p>For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?</p>					<p>1</p>
<p>2</p>	<p>3</p> <p>Labor Day</p>	<p>4</p>	<p>5</p>	<p>6</p>	<p>7 STP <input type="checkbox"/></p>	<p>8</p>
<p>9</p>	<p>10</p>	<p>11</p>	<p>12</p>	<p>13</p> <p>DEQ Asbestos & Lead Workshop - Baton Rouge (225) 219-3049</p>	<p>14 STP <input type="checkbox"/></p>	<p>15 **</p>
<p>16</p>	<p>17</p>	<p>18</p>	<p>19</p> <p>UST Training - Lafayette (225) 219-3713 8-12 Noon</p>	<p>20</p>	<p>21 STP <input type="checkbox"/></p>	<p>22</p>
<p>23</p> <p>##</p> <p>30</p>	<p>24</p> <p>## Stage II Certificates Expire on 30th</p>	<p>25</p>	<p>26</p> <p>SWAT- Lake Charles (225) 219-3720 8-12 Noon</p>	<p>27</p>	<p>28 STP <input type="checkbox"/></p> <p>**</p>	<p>29</p> <p>Ozone Season Ends</p>

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



October 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Keep paint & solvent usage records if required.	1	2	3	4 UST Worker Certification Exam (225) 219-3062	5 STP <input type="checkbox"/>	6
7	8	9	10	11	12 STP <input type="checkbox"/>	13
14	15 **	16	17	18 UST Training - New Orleans (225) 219-3713 1-5 pm	19 STP <input type="checkbox"/>	20
21	22	23	24	25 SWAT- Hammond TBA (225) 219-3720 8-12 Noon	26 STP <input type="checkbox"/>	27
28 ** Quarterly DMR Due	29	30	31		For <u>sanitary treatment plants (STP)</u>, check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



November 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Check Air Permit. Keep paint & solvent usage records if required.		For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?		1 UST Worker Certification Renewal Due	2 STP <input type="checkbox"/>	3
4 Daylight Saving Time Ends	5	6 Election Day	7	8	9 STP <input type="checkbox"/>	10
11	12	13	14	15 **	16 STP <input type="checkbox"/>	17
18	19	20	21	22 Thanksgiving Day	23 STP <input type="checkbox"/>	24
25	26	27	28 **	29 UST Train. (225) 219-3713 SWAT- (225) 219-3719	30 STP <input type="checkbox"/>	

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)



December 2007 Small Business Reporting Calendar



Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
For sanitary treatment plants (STP), check weekly: (1) compressor, (2) chlorine in chlorinator & in contact with wastewater?, (3) foul odors from discharge, is discharge cloudy?		Check Air Permit. Keep paint & solvent usage records if required.	QUESTIONS? 1-800-259-2890	***UST Worker Certification expires on 31st		1
2	3	4	5	6 UST Worker Certification Exam (225) 219-3062	7 STP <input type="checkbox"/>	8
9	10	11	12 UST Training - Lake Charles (225) 219-3713 8-12 Noon	13	14 STP <input type="checkbox"/>	15 **
16	17	18	19	20	21 STP <input type="checkbox"/>	22
23	24	25	26	27	28 STP <input type="checkbox"/> **	29
30		*** 31 Christmas Day				

Check water discharge permit: daily visual monitoring for wastewater oil sheen required? All storm water pollution prevention plans require annual self-inspections.

Check water permit for proper monitoring & schedule reporting monthly, quarterly, semiannually & annually (DMRs)