

Louisiana Vehicle Emission Inspection Report

Test Date/Time: 01/25/2007 10:57:35 AM

Safety Sticker Number
12345678

Emission Sticker Number
E-1 1234567

Rejection Sticker Number
N/A

VEHICLE/DRIVER INFORMATION

Drivers License	1234567	Odometer:	123,456	Model:	CROWN VICTORIA LX
Year:	2003	Make:	FORD	Cylinders:	8
VIN:	1FAFLP23C24D76521	Engine Size:	4600CC	Inspection Type:	Initial
GVWR:	5500	Vehicle Plate:	ABC789		
Fuel Type:	Gasoline	Previous Test Date:	N/A		

VISUAL INSPECTION

Catalyst:	Passed	PCV System:	Passed	Air Injection System:	Passed
Evaporative System:	Passed	EGR System:	Passed		

SAFETY INSPECTION

Current Plate/Registration Inspection:	Passed	Light Inspection:	Passed
VIN Matches Registration:	Passed	Headlamps:	Passed
Registration:	Passed	Dimmer Switch:	Passed
Plate:	Passed	Concealment Devices:	Passed
Plate Condition/Mounting:	Passed	Lamp Height:	Passed
Liability Insurance:	Passed	Parking Lamps:	Passed
Drivers License Expiration:	Passed	Turn Signals:	Passed
		High Mount Brake Lamp:	Passed
Glass/Wipers & Washer Inspection:	Passed	Stop Lamps:	Passed
Windshield Wipers:	Passed	Tail Lamps:	Passed
Windshield Washer:	Passed	Back-up Lamps:	Passed
Window Tint:	Passed	License Plate Lamps:	Passed
Cracks:	Passed		
Body/Doors Inspection:	Passed	Interior Inspection:	Passed
Body/Sheet Metal:	Passed	Floor Plan:	Passed
Fenders:	Passed	Seatbelts:	Passed
Bumpers:	Passed	Horn:	Passed
Doors and Latches:	Passed		
Hood Latch:	Passed	Test Drive:	Passed
		Brakes:	Passed
Wheels/Tires:	Passed	Suspension:	Passed
Exhaust/Muffler/Fuel System:	Passed	Speedometer:	Passed
Visible Smoke:	Passed	Odometer:	Passed
		Steering:	Passed

Louisiana Vehicle Emission Inspection Report

GAS CAP INSPECTION

Gas cap adapter available: Yes Gas cap replaced: N/A

OBDII Readiness

Misfire	Ready	Sec. Air	Not Supported
Fuel System	Ready	A/C System	Not Supported
Component	Ready	O2 Sensor	Ready
Catalyst	Ready	O2 Heated	Ready
Heated Cat.	Not Supported	EGR	Ready
Evap. System	Ready		

OBDII OVERALL READINESS RESULT: Ready

OBDII Trouble Codes

No trouble codes.

Commanded MIL Result:	Pass
Engine Off MIL check result:	Pass
Engine Running MIL check result:	Pass

OBDII Connector Result:

Connector Found

OBDII Communication Result:

OBDII Message

Based on information obtained from the On-Board Diagnostic (OBD) system, the pollution control system on this vehicle is operating properly.

EMISSION CONTROL SYSTEMS INSPECTION

Visual Inspection:	Passed
Safety Inspection:	Passed
Gas Cap Inspection:	Passed
OBDII Inspection:	Passed

OVERALL TEST RESULT: PASS

PLEASE RETAIN THIS COPY FOR YOUR RECORDS

Station Name:	ACME Inspections	Station Number:	P1998
Address:	123 Cactus Way	Software Version:	2.15
Phone:	555-1212	Inspector ID:	wecoyote
Record Number:	21578		
Amount Paid:	\$18.00		

Inspector Signature: _____